

溶接サドル継手 入個表

枝管	主管	白品		黒品	
		ねじ込み	差込	ねじ込み	差込
1/2	11/2	50	50	50	50
	2	50	50	50	50
3/4	21/2	50	50	50	50
	3	50	50	50	50
	4	50	50	50	50
1	11/2	35	35	35	35
	2	35	35	35	35
	21/2	35	35	35	35
	3	35	35	35	35
	4	35	35	35	35
	5	35	35	35	35
	6	35	35	35	35
11/4	21/2	20	20	20	20
	3	20	20	20	20
	4	20	20	20	20
	5	20	20	20	20
	6	20	20	20	20
11/2	21/2	15	15	15	15
	3	15	15	15	15
	4	15	15	15	15
	5	15	15	15	15
	6	15	15	15	15
	8	15	15	15	15
2	21/2	8	8	8	8
	3	20	10	10	10
	4	20	10	10	10
	5	20	10	10	10
	6	20	10	10	10
	8	20	10	10	10
21/2	3	4	4	4	4
	4	12	7	7	7
	5	12	7	7	7
	6	12	7	7	7
	8	12	7	7	7
3	4	3	3	3	3
	5	8	3	3	3
	6	8	3	3	3